





How to sling/crane lift FAB Bench 700 & 500

Patent Pending GB 2543079 & WO2017/060711
Crane Lifting Certified



Check all plastic bolts are tightened to ensure table tops are secure for lift



SAFE SLINGING:

1. Check to ensure the dual lockdown of the whirley nuts are secure. Check all the plastic bolts are tightened to secure table tops for a safe lift. Please ensure the bench is cleaned of loose fabrication work. No objects are to be carried on the bench during lift.
2. Position the sling underneath the string and hook into the inner notched location points. This notch location point reduces the sling from slipping along the string.
3. Connect all slings to the central lifting chain for a balanced lift, as noted in the images above.